

Connect Settings Exit

Log

```
ADL: Check mode
ADL: phone is in flash mode

Backup enabled, will read all certificates...
Reading NPC certificate...
Reading CCC certificate...
Reading HWC certificate...
Reading R&D certificate...
Reading VARIANT certificate...
Reading PARTNERC certificate...
Reading MDM_KEYS certificate...
- > No any CRT data (MCU damaged/CERT erased), skip saving

SimLock Data saved...
SimLock Key saved...
WMDRM_PD Data saved...

RPL saved : C:\Users\User\סמ\שונות\תוכנות\י\InfinityBEST\Backup\Cert\20_01_2021_

===Flashing [MCU]===
Erase : Processing rm721_11.40.mcusw
Partitioning....
Partitioning error! Phone Not respond!
Connect phone on selected interface...

Elapsed: 00:00:39
Connect phone on selected interface...
```

Service Tool User Data Tool Misc **Flashing** Repair Unlock nTab

Flash File Select

Save INI As... Use INI Manual Use User INI Select mode RA-6

<input checked="" type="checkbox"/>	rm721_11.40.mcusw	MCU
<input checked="" type="checkbox"/>	כשר ללא ציפופים.ppm_f	PPM1
<input type="checkbox"/>		PPM2
<input checked="" type="checkbox"/>	rm721_11.40.image_f_059D660_repacked	CNT1
<input type="checkbox"/>		CNT2
<input type="checkbox"/>		CNT3

Flash Settings

DeadMode Downgrade Backup

After Flash

Chk/Read Set Normal ChangePC Reset LT FactorySet

Flash Mode Settings

Check FLASH

0%

Disconnected USB READY 16:16:50